


Instructions for etched Universal Joint




Two options are provide depending on the space available

The two halves of the UJ etch are folded over trapping a piece of 0.3mm steel wire in the half-etched slot and the assembly then soldered together

The other part of the UJ can be formed from a suitable piece of rod slotted to take the tabs on the etch part with sufficient clearance in the slot to allow free movement backwards and forwards

The other end of the UJ can be made from a trapped loop as shown



Detail of trapped end of UJ